

LEWES BPW

Howard Seymour Water Reclamation Plant

Operation and Maintenance Report



May 2022

Executive Summary

| | Green | Yellow | Red |
|------------------|-------|--------|-----|
| Headworks | | | |
| Oxidation Ditch | | | |
| Filters | | | |
| Generator | | | |
| Weather | | | |
| Solids Handling | | | |
| NPDES Parameters | | | |
| Pump Stations | | | |
| Personnel | | | |
| Safety | | | |
| Compliance | | | |

(New information in bold font)

- Headworks- Inframark continues to utilize the dewatering roll off container to capture screening while lipactor is offline.
- Filters- De-ragging UF Train 4 was completed during the week of 12-27-2021. Deragging UF Train 1 was completed during the week of 5-16-2022. UF Train 2 Deragging began during the week of 6-6-2022. Anticipated completion week of 6-27-2022.
- Pump Stations- Pump Station 8 Generator Transfer Switch replacement was completed 6-21-2022. A rental emergency generator is online at Pump Station 4 while plans for a permanent solution are being evaluated. Sprig competed install of cleanouts to each pump suction line at PS4 during the week of 5-16-2022. PS9 wet-well pipe replacement and bypass install was completed during the week of 6-13-2022. Three Classic T8 rotating assemblies for PS3 were purchased from Freemire and Associates. The assemblies will be installed when additional parts for the rebuild are received. A contractor completed hydro-excavating at PS3 to locate the force main for future installation of bypass connections. Approval for a proposal to replace wet well piping in PS2 is required.
- Personnel- Currently Inframark has 5 fulltime and one part-time employees assigned to the Lewes Facilities.

Critical Issues

- Covid- Inframark is following CDC recommendations to ensure undisrupted service to the BPW and the Lewes community.
- Condition of headworks screening equipment is in critical need of repair or replacement to decrease excessive ragging of UF membranes.
- Spare pumps are not in stock for PS11, PS15, PS16, PS17, PS17B, PS18 and PS32. Inframark does not have maintenance records for existing pumps. Based on recommendations made in Severn Trent's 2016 Annual Report, most pumps were in need of replacement within five years. We have found no evidence that these pumps had been replaced during the past five years. Many pump station control panels are in

need of repair or replacement including PS1, PS2, PS5, PS6, PS7, PS9, PS10, PS11, PS12, PS13, PS14, PS15, PS16, PS17, PS18, PS33, PS74 and PS83.

Projects

| Project | Status | Priority Level | Approval | Est. Complete Date |
|-------------------------------------|---|-------------------|-------------|--------------------------|
| Headworks Replacement | In design | High | BPW Project | QTR4 2022 |
| Replace Generator and ATS at PS4 | GMB and Keystone are evaluating size based on future needs | High | BPW Project | QTR2 2022 |
| Replace ATS at PS8 | Complete | High | Received | QTR2 2022 |
| Rehab Pumps at PS3 | Rotating assemblies received | High | Recieved | QTR3 2022 |
| Replace wet-well piping PS2 | Proposal from Sprig submitted to BPW | High | Needed | QTR3 2022 |

Operations

NPDES Permit Compliance

- Please review the following tables that summarize NPDES reporting criteria for May 2022. No violations will be reported for May. The DMR will be forwarded upon completion.
- The average daily influent flow for May was 0.766 MGD with a maximum daily flow of 0.996 MGD. Precipitation totaled 2.52 inches for May with a maximum daily total of 0.6 inches.

| | Max | Sum |
|------------------------|------|------|
| Precipitation (inches) | 0.59 | 2.52 |


| Influent | Limit | Average | Min | Max | Vio |
|------------|-------|---------|-------|-------|-----|
| Flow (MGD) | | 0.766 | 0.605 | 0.996 | |
| BOD (mg/L) | | 146 | 146 | 146 | |
| TSS (mg/L) | | 85 | 85 | 85 | |

| Effluent | Limit | Average | Min | Max | Vio |
|------------------------------|---------------------|---------|--------|--------|-----|
| Flow (MGD) | | 0.779 | 0.653 | 0.999 | Ν |
| Dissolved Oxygen (mg/L) | | 6.35 | 5.11 | 7.29 | Ν |
| pH (SU) | Min 6/ Max 9 | 7.29 | 7.08 | 7.69 | Ν |
| Enterococcus (col/100ml) | Avg 10/ Max 104 | <1 | <1.0 | <1.0 | Ν |
| BOD (mg/L) | Avg 15/ Max 23 | <2.4 | <2.4 | <2.4 | Ν |
| BOD Load (lbs) | Avg 188/ Max 288 | <15 | <14 | <17 | Ν |
| BOD Removal (%) | | 98.4 | 98.4 | 98.4 | |
| TSS (mg/L) | Avg 15/ Max 23 | <0.5 | <0.5 | 0.5 | Ν |
| TSS Load (lbs) | Avg 188/ Max 288 | <3 | 3 | <4 | Ν |
| TSS Removal (%) | | 99 | 99 | 99 | |
| Total Nitrogen (mg/L) | Avg 8 | 7.47 | 5.73 | 9.21 | Ν |
| Total Nitrogen Load (lbs) | Avg 100 | 40.45 | 31.02 | 49.87 | Ν |
| Total Phosphorous (mg/L) | Avg 2 | 0.26 | 0.26 | 0.26 | Ν |
| Total Phosphorous Load (lbs) | Avg 25 | 1.57 | 1.57 | 1.57 | Ν |
| Process | | | | | |
| Bio #1 MLSS (mg/L) | | 8,950 | 8,000 | 10,100 | |
| Bio #2 MLSS (mg/L) | | 9,125 | 8,200 | 10,200 | |
| Train 1 MLSS (mg/L) | | 9,400 | 9,400 | 9,400 | |
| Train 2 MLSS (mg/L) | | 9,275 | 7,700 | 10,200 | |
| Train 3 MLSS (mg/L) | | 8,875 | 7,600 | 10,000 | |
| Train 4 MLSS (mg/L) | | 10,000 | 9,500 | 11,000 | |
| TSS Digester 1 (mg/L) | | 17,450 | 16,600 | 18,400 | |
| TSS Digester 2 (mg/L) | | 16,700 | 15,700 | 17,400 | |

| | Average | Мах | Sum |
|-------------------------|---------|--------|---------|
| Sludge Wasted (gallons) | 10,761 | 23,698 | 322,834 |


Sludge Operations and Disposal


| Liquid Hauled | 65,000 | Gallons | DELCORA |
|----------------------|--------|----------|---------------|
| Cake Hauled | 52.8 | Wet Tons | Sussex County |
| Dewatering Container | 5,300 | Gallons | DELCORA |



Trends Influent vs Precipitation Trend Previous 12 Months

Effluent Biological Contaminants Trend Previous 12 Months





Effluent Nutrient Trends Previous 12 Months

Maintenance, Repair and Activities

| 5-09-2022-WWTP- 5-09-2022-PS3- 5-10-2022-WWTP- | Inframark repaired feed line to CIP Sodium Hypochlorite Pump A. Inframark added oil to Pump 2. Inframark relocated Process Caustic Feed Pump air bleeder valve to the |
|---|---|
| 5-10-2022-PS4- | discharge side of pump. Inframark unclogged Pump 2. |
| 5-13-2022-PS4- | Inframark discovered Pump 2 clogged again, removed ragging from the check valve and returned to service. |
| 5-16-2022-WWTP- 5-23-2022-WWTP- 5-24-2022-PS32- | Inframark replaced chemical feed line to the Process Caustic Feed Pump. Inframark repaired the discharge hose from the sump pump in MH 4. Inframark discovered Pump 2 clogged, removed rags from volute and |
| 5-27-2022-PS3- 5-31-2022-WWTP- | returned to service. Inframark added oil to Pump 2, reprimed and returned to service. Inframark replaced floats to sump pumps in MH4 and MH5. |
| 5-31-2022-WWTP- | Inframark replaced the sensor cap to LDO Probe 1B, calibrated and returned to service. |
| 5-31-2022-PS3- | Inframark added oil to Pump 2, reprimed and returned to service. |

Afterhours Alarm Callouts

| 5-01-2022-WWTP- | UF Train 2 High Turbidity Alarm |
|-----------------|---------------------------------|
| 5-07-2022-WWTP- | UF Train 3 High Turbidity Alarm |
| 5-20-2022-WWTP- | UF Train 1 High Turbidity Alarm |
| 5-28-2022-WWTP- | UF Train 3 High Turbidity Alarm |

Maintenance Budget

| Monthly Budget | May 2022 | Contract Year to Date | Over |
|----------------|--------------|-----------------------|-------------|
| \$6,667 | \$ 12,793.95 | \$128,999.95 | \$48,999.95 |

Maintenance Expenditures

| Vendor | Description | Expense |
|--------------------------------------|--|----------|
| Xylem Dewatering Solutions, Inc. | Bypass pump rental August/September Emergency Opening Charge | 410.00 |
| Xylem Dewatering Solutions, Inc. | Bypass pump rental Nov/Dec Rental 11/07/2021 thru 12/04/2021 | 4,064.89 |
| Hill's Electric Motor Service Inc | Gorman Rupp reuse water pump rotating assembly repair. Job # 56804 | 1,527.32 |
| K & Z Mechanical, Inc. | Electrician; Disconnect and reconnect cord to RAS Pump; connect twist lock cord connectors for Grit System Vacuum Pump; Install new ground bar; Check 3-pole contactor of motor and change thermal overloads due to nuisance tripping. | 665.00 |
| K & Z Mechanical, Inc. | Materials: twist lock, male and female cord connectors, 4" ground terminals, thermal overloads | 168.00 |
| UNTD RNTLS | Rental Generator PS4 | 1,668.56 |
| HACH COMPANY | Composite Sampler Tubing | 101.74 |
| USA BLUE BOOK | Replacement Composite Sampler Refrigerator Thermometers. | 151.02 |
| USA BLUE BOOK | Digital verification thermometers | 144.04 |
| FRESHWATERSYSTEMS | Membrane O-ring lubricant | 106.14 |
| THE HOME DEPOT | Drain covering for membrane cleaning | 39.48 |
| THE HOME DEPOT | Membrane sprinkler replacement. | 45.96 |
| FISHER AUTO PARTS | Oil absorbent | 27.98 |
| THE HOME DEPOT | Digester return pump replacement and parts | 406.83 |
| LOWES | Plumbing parts for chemical feed air relief caustic | 23.50 |
| LOWES | Chemical feed parts, caustic pump air purge | 20.84 |
| LOWES | Solid's dumpster tarp bungy cords & safety corners | 25.96 |
| Hill's Electric Motor Service Inc | Gorman Rupp Super T6 6" rotating assembly rebuild Job # 58437 | 3,196.69 |

Health & Safety

- As of May 31, 2022, Inframark staff have worked 589 days at the Lewes Facilities without a lost time injury.
- Inframark Training and Presentations
 - > Offsite Arc Flash Electrical training for Maintenance Tech III
 - > NFPA 70E Electric Safety in the Workplace
 - Incident Reporting Definitions and Responsibilities 2022

Personnel

| Name | Title | DE Certification |
|-------------------|----------------------------|--------------------|
| Jerry Shupe Jr. | Regional VP | NA |
| Michael Wolgemuth | Regional Manager | DE Class IV WW |
| Richard Plack | Project Manager | DE Class IV WW |
| Paul Smith | Operator II | DE Class II WW |
| Vince Catalano | Lead Operator | DE Class II OIT WW |
| Kurt Brittingham | Operator II | NA |
| Michael Mazzetti | Maintenance Technician III | NA |
| David Weed | PT Operator III | DE Class IV WW |
| Tom Callahan | Regional Safety Advisor | NA |

Attachments

- May Sussex County Flow Totals
- April DMR
- Zenon InSight Report- 6-01-2022
- Zenon InSight Report- 5-18-2022