Electric Outages Lewes BPW

Month	Date	Circuit	Customers Interrupted	Duration	Cause	Percent System Reliability
January 2018	1/12/2018 1/20/2018 1/20/2018	3 2 1	32 5 1	180 30 30	Equipment Damage Squirrel	99.99645%
February 2018	No outages	1	1	30	Squirrel	100%
March 2018	3/6/2018	3	647	150	Equipment Damage	99.94218%
April 2018	4/5/18 4/15/18 4/18/18 4/22/18 4/23/18	1 4 1 4	540 630 3717 1 1	75 80 188 45 20	Lightning Tree Utility Maintenance & Repairs Squirrel Squirrel	99.51366
May 2018	5/12/18	3	1	45	Equipment worn	99.99997%
June 2018	No outages					100%
July 2018	7/28/18 7/29/18	2 2	5 8	60 60	Bird Squirrel	99.99954%
August 2018	8/5/18 8/10/18 8/11/18	1 1 4	4 1 1	45 120 120	Squirrel Equipment Damage Equipment Damage	99.99975%
September	9/8/18 9/8/18 9/26/18	1 2 2	4 1 2	60 60 15	Equipment worn out Equipment worn out Equipment worn out	99.99998%
October	10/15/18 10/16/18 10/17/18 10/18/18 10/22/18 10/27/18	1 2	3717 3717 3717 3717 4 20	256 256 301 211 60 120	Equipment replacement Equipment replacement Equipment replacement Equipment replacement Squirrel Equipment Worn out	97.73437%
November	11/16/18 11/25/18	1 4	4 1	45 60	Squirrel Squirrel	99.9985%